

## FISCHBACH-AXIAL-FANS - A/AW-series - diagram overview - speed controller assignment -

### assignment of FISCHBACH SPEED CONTROLLERS/-AUTOMATIC CONTROLLERS

Axial-fans		automatic control		control		control	
				stepless		stepwise	
				with casing, control knob and scale		with casing and stepped switch (single-phase motor 7 steps, three-phase-motor 5 steps)	
type	$I_{max}$ [A]	type	part no.	type	part no.	type	part no.
<b>single-phase 230V, 1N~ 50 Hz</b>							
AW 315/ E15	1,55	FRA 32	6251	FDR 32	6162	FDR420	6201
AW 350/ E15	1,60	FRA 32	6251	FDR 32	6162	FDR 420	6201
AW 420/ E15	1,9	FRA 32	6251	FDR 32	6162	FDR 420	6201
AW 500/ E35 A 500/ E 35	3,8	FRA 55	6252	FDR 55	6163	FDR 420	6201
	4,3						
AW 560/ E35	4,5	FRA 55	6252	FDR 55	6163	FDR 420	6201
A 560/ E 65	6,10	FRA 80	6253	FDR 80	6164	FDR 750	6202
A 630/ E 80	10,70	FRA 120	6255	FDR 120	6165	FDR 1300	6204
<b>three-phase 400V, 3N~ 50 Hz</b>							
A 500/ D 500	2,47	FRA 55/3	6281	FDR 55/3	6231	FDR 2.75/3	6181
AW 630/ D850	2,8	FRA 55/3	6281	FDR 55/3	6231	FDR 5.5/3	6172
A 630/ D 1	5,50	FRA 55/3	6281	FDR 55/3	6231	FDR 5.5/3	6172

